

# INTERNATIONAL INSTITUTE OF WELDING

Having satisfied the requirements of the IIW  
Manufacturer Certification Scheme according to  
ISO 3834

Company: **NORTH EASTERN RAILWAY**  
The Unit: **MECHANICAL WORKSHOP**  
Located in: **IZATNAGAR, BAREILLY, UP - 243 122 (INDIA)**  
is certified in accordance with

## ISO 3834 Part 2

For the product(s): **PERIODIC OVERHAULING OF RAILWAY COACHES AND WAGONS**

with the scope of work stated in the attached Schedule

Certificate number and revision status: **MCS:IN:17:13 – Rev. 0**

First Issue date: **14.10.2017**

Current issue date: **14.10.2017**

Date of expiry: **13.10.2020**

ANBCC Governing Board Representative



**BIRENDRA KUMAR MISHRA**

The Indian Institute of Welding-ANBCC

Scheme Manager

**RANAJOY BANERJEE**

The Indian Institute of Welding-ANBCC




This Certificate is subject to the rules established by IIW  
for the certification of Companies





# IIW Manufacturer Certification Scheme



## SCHEDULE

Extent of validity of IIW Certificate N° MCS:IN:17:13 Rev.0

Product standard(s):

RDSO STANDARD ICF STANDARD

Alternative Standard(s) (refer to ISO 3834 – 5)

ISO 9606-1 ASNT-TC-1A

Welding process(ISO 4063)	Parent material groups(ISO/tr 15608)
111	1.1, 1.2, 1.3
135	1.1, 1.2, 1.3

Responsible Coordination Personnel:

Name	Qualification	Job function and level***
Pankaj Kumar Kushwaha (RWC)	IWT	Comprehensive

\*\*\* The level must be stated in order to comply with ISO 14731

ANBBC Governing Board Representative


Scheme Manager

BIRENDRA KUMAR MISHRA

RANAJAY BANERJEE

The Indian Institute of Welding-ANBCC

The Indian Institute of Welding-ANBCC



The standards and documents referred in the certificate and  
schedule are those valid at the time of certification

